



## CFA633 v1.5a to v1.5c hardware changes

1. Increased clearance at each mounting hole
  2. Improved backlight circuit
  3. Addition of 5KΩ resistor for JP9 (previously closed with 0403 5KΩ resistor)
  4. JP8 and JP9 relocated
  5. Change to stainless steel bezel for improved ESD protection
- All headers in same location
  - All mounting holes in same location and same size
  - No changes in functionality
  - **NO FIRMWARE CHANGES**

