






Crystalfontz America Inc.

12412 E. Saltese Ave. Spokane Valley WA 99216
 (888) 206-9720 www.crystalfontz.com

TITLE: CFA-10003		BY: Tom Shearer	
Description: CFA-10003 1" Demo Board			REV: 1.3
Date: 4/12/2011 8:11:54 AM		Sheet: 1/5	



Crystalfontz America Inc.

12412 E. Saltese Ave. Spokane Valley WA 99216
(888) 206-9720 www.crystalfontz.com

TITLE: CFA-10003

BY: Tom Shearer

Description:





CFA-10003 1" Demo Board











REV:

1.2

Date: 4/12/2011 8:11:54 AM

Sheet: 2/5





Crystalfontz America Inc.

12412 E. Saltese Ave. Spokane Valley WA 99216
(888) 206-9720 www.crystalfontz.com

TITLE: CFA-10003

BY: Tom Shearer

Description:

CFA-10003 1" Demo Board


REV:

1.2

Date: 4/12/2011 8:11:54 AM

Sheet: 4/5

Rev	Date	By	Release Notes
1.0	March 13 2009	Mark Williams	Initial Release, based on +3.3V core design
1.1	June 12 2010	Tom Shearer	Change to 3.3V 1A DC-DC regulator circuit, misc component renumbering, net renaming. Rotate CFA-10004 module (LCD5), shift other displays to align.
1.2	Aug 9, 2010	Tom Shearer	Change J7, the microSD card socket, from 3M part to JAE ST9 part. Modify layout of IC2 to provide larger copper heat sink planes on both sides.
1.3	Apr 4, 2011	Tom Deutschman	Replaced input, output caps around IC2 with MLCC caps Tightened up the layout of area around IC2

 CrystalFontz America Inc. 12412 E. Saltese Ave. Spokane Valley WA 99216 (888) 206-9720 www.crystalfontz.com		
TITLE: CFA-10003		BY: Tom Shearer
Description: CFA-10003 1" Demo Board		REV: 1.2
Date: 4/12/2011 8:11:54 AM		Sheet: 5/5