1:1 Outline Drawing CFAP1602B





Be sure to set “Page Scaling” to “None” in the Acrobat print dialog.
Always verify print accuracy with physical part, or by measuring the printout.