


Getting Started Guide

Bring up the CFAL12864K using
the Generic Adapter Board CFA10102

Configured for SPI



Color Guide

- 1uF Capacitor
- 0.1uF Capacitor
- 0Ω Resistor
- 4.7uF Capacitor
- 1MΩ Resistor

*Note: Don't forget to set the appropriate voltage at HV!

Solder each position with the corresponding component as specified in the color guide. All land patterns are for 0603 Components.

Crystallfontz America, Inc
www.crystallfontz.com